



## PROJECT CASE STUDY



Coping and kneeler blocks were supplied to all the gable features



We supplied individually tailor made units for each of the renovated areas



The original natural stone walling is complemented by the new cast stone

### Replacement of old stone architectural features with cast stone replicas

#### Client

Private homeowner

#### Location of Project

Lartington, near Barnard Castle

#### Project Overview

As part of the renovation of this attractive period property, we supplied cast stone copings and corbel blocks to replace the original natural stone features which had suffered deterioration over time.

#### Project Notes

There were several challenges to this project, including the need for very accurate colour matching, plus the need to include 'cast-in' lifting inserts to the some of the products due to their considerable weight.

#### Client Feedback

"Thanks for your help and advice, you've been great to deal with!  
I have to say both the builder and I were very impressed with the product. Great finish, consistent, easy to work with and exactly what we ordered. Also, the pointing mix made a superb finish compared to normal mortar."

**More Case Studies visit [www.caststoneuk.co.uk/case-studies](http://www.caststoneuk.co.uk/case-studies)**

**RES-18**

Procter Cast Stone  
Isabella Road, Garforth  
Leeds, LS25 2DY  
Tel: 0113 286 3329  
Fax: 0113 287 6284  
[websales@proctergarforth.co.uk](mailto:websales@proctergarforth.co.uk)



[www.caststoneuk.co.uk](http://www.caststoneuk.co.uk)